

A

Appendix A: Stage 1 Archaeological Assessment Report - Images



9 IMAGES

Image 1: Regional Road 25 at Speers Road – Road and Sidewalk

Looking South



Image 2: Regional Road 25 Lakeshore West Rail Overpass – Grading and Utility Installation

Looking North



Image 3: Regional Road 25 Lakeshore West Rail Overpass – Grading and Sidewalk

Looking South



Image 4: Regional Road 25 South of QEW - Grading

Looking North



Image 5: West of Regional Road 25 at QEW Overpass – Grading Adjacent to Bronte Creek

Looking North



Image 6: West of Regional Road 25 at QEW Overpass – Grading Adjacent to Bronte Creek

Looking West



Image 7: Regional Road 25 at QEW Interchange

Looking North



Image 8: South of Regional Road 25 – Grading Adjacent to QEW and Bronte Creek

Looking East



Image 9: South of Regional Road 25 – Grading Adjacent to QEW and Bronte Creek

Looking North



Image 10: South of Regional Road 25 – Drainage to QEW and Bronte Creek

Looking South



Image 11: Regional Road 25 and QEW Interchange

Looking North



Image 12: Regional Road 25 North of QEW

Looking North



Image I3: Regional Road 25 North of QEW – Driveway and Sidewalk

Looking South



Image I4: Regional Road 25 – Berm and Sidewalk

Looking Southwest



Image 15: Regional Road 25 – Sidewalk and Fallow Fields

Looking South



Image 16: Upper Middle Road at Regional Road 25 – Grading and Utility Installation

Looking West



Image 17: Regional Road 25 at Upper Middle Road – Grading and Sidewalk

Looking North



Image 18: Regional Road 25 North of Upper Middle Road and Fourteen Mile Creek – Grading and Sidewalk

Looking North



Image 19: Regional Road 25 – Grading and Sidewalk

Looking South



Image 20: Regional Road 25 Lakeshore West Rail Overpass – Grading and Utility Installation

Looking North



Image 21: Regional Road 25 North of West Oak Trail – Grading, Utility Installation, and Sidewalk

Looking North



Image 22: Regional Road 25 at Khalsa Gate – Under Construction

Looking North



Image 23: West of Regional Road 25 at Pine Glen Road – Under Construction

Looking North



Image 24: West of Regional Road 25 South of Dundas Street West – Sidewalk and Grading

Looking South



Image 25: Regional Road 25 North of Dundas Street – Cultivated Field

Looking South



Image 26: Regional Road 25 North of Dundas Street West – Cultivated Field

Looking North



Image 27: Regional Road 25 North of Dundas Street West – Cultivated Field

Looking South



Image 28: Regional Road 25 and Old Bronte Road - Driveways

Looking South



Image 29: Regional Road 25 South of Highway 407 - Grading

Looking North



Image 30: Regional Road 25 South of Highway 407 – Cultivated Field

Looking South



Image 31: Regional Road 25 at Burnhamthorpe Road West – Parking Lot and Building

Looking North



Image 32: Regional Road 25 North of Highway 407 – Cultivated Field

Looking South



Image 33: Regional Road 25 South of Burnhamthorpe Road West – Grading

Looking South



Image 34: Regional Road 25 North of Burnhamthorpe Road West -Grading

Looking East



Image 35: Regional Road 25 South of Henderson Road - Grading

Looking North



Image 36: Regional Road 25 South of Henderson Road – Grading and Cultivated Field

Looking South



Image 37: Regional Road 25 at Henderson Road – Grading

Looking North



Image 38: Regional Road 25 North of Henderson Road – Cultivated Field

Looking South



Image 39: Regional Road 25 Lakeshore West Rail Overpass – Buried Utilities and Cultivated Fields

Looking Northeast



Image 40: Regional Road 25 South of Lower Base Line – Wide Ditch and Grading

Looking North



Image 41: Regional Road 25 South of Lower Base Line – Wide Ditch and Stripped Topsoil

Looking South



Image 42: Regional Road 25 South of Lower Base Line – Wide Ditch and Stockpiled Soil

Looking South



Image 43: Regional Road 25 South of Lower Base Line – Wide Ditch and Grading

Looking North



Image 44: South of Regional Road 25 – Berm and Cultivated Fields

Looking South



Image 45: Regional Road 25 at Halton Waste Management Site

Looking South



Image 46: Regional Road 25 at Halton Waste Management Site - Grading

Looking South



Image 47: Regional Road 25 - Driveway

Looking West



Image 48: Regional Road 25 – Wide Ditch and Grading

Looking North



Image 49: Regional Road 25 – Graded Private Property

Looking North



Image 50: Regional Road 25 – Cultivated Field

Looking North



Image 51: Regional Road 25 at Britannia Road – Graded Gravel Parking Lot

Looking Northeast



Image 52: Regional Road 25 North of Britannia Road – Graded for Creek Rehabilitation

Looking West



Image 53: Regional Road 25 at Upper Middle Road – Driveway and Septic Tank

Looking Northeast



Image 54: Regional Road 25 at Ethridge Avenue – Sidewalk and New Intersection Construction

Looking North



Image 55: Regional Road 25 at Etheridge Avenue – Parking Lot and Road Construction

Looking South



Image 56: Regional Road 25 South of Izumi Gate – Parking Lot and Grading

Looking South



Image 57: Regional Road 25 North of Izumi Gate – New Condominium Construction

Looking South



Image 58: Regional Road 25 at Saint Clair Masonic Lodge

Looking North



Image 59: Regional Road 25 South of Louis St. Laurent Avenue – Cultivated Field

Looking Northeast



Image 60: Regional Road 25 South of Louis St Laurent Avenue – Berm and Fallow Field

Looking West



Image 61: Regional Road 25 South of Sixteen Mile Creek – Steep Slope

Looking West



Image 62: Regional Road 25 – Grading and Driveway Construction

Looking North



Image 63: Regional Road 25 and Sixteen Mile Creek Valley

Looking West



Image 64: Regional Road 25 – Sidewalk and Driveway

Looking North



Image 65: Regional Road 25 South of Derry Road – Grading and Sidewalk

Looking North



Image 66: Regional Road 25 South of Derry Road – Parking Lot and Driveway

Looking South



Image 67: Regional Road 25 at Bowes Cemetery

Looking South



Image 68: Regional Road 25 at Bowes Cemetery

Looking South

